

TABLAS DE TEMPERATURA

Termopar tipo K rango: -100 +400°C

Temperatura °C	mv Termopar	Salida Voltios	Grados 10mV/°C	Error grados
-80	-2.920	0.193	-80.67	-0.67
-40	-1.527	0.590	-40.98	-0.98
0	0	1.000	-0.03	-0.03
50	2.023	1.496	49.60	-0.40
100	4.096	2.005	100.46	0.46
150	6.138	2.506	150.56	0.56
200	8.138	2.996	199.63	-0.37
250	10.153	3.491	249.06	-0.94
300	12.209	3.995	299.50	-0.50
350	14.293	4.506	350.63	0.63
400	16.397	4.998	399.80	-0.20

Termopar tipo K rango: 1250°C

Temperatura °C	mv Termopar	Salida Voltios	Grados 4mV/°C	Error grados
50	2.022	0.197	49.26	-0.74
100	4.095	0.399	99.77	-0.23
200	8.137	0.793	198.25	-1.75
300	12.207	1.190	297.42	-2.58
400	16.395	1.598	399.45	-0.55
500	20.64	2.012	502.88	2.88
600	24.902	2.427	606.72	6.72
700	29.128	2.839	709.69	9.69
800	33.277	3.243	810.77	10.77
900	37.325	3.638	909.40	9.40
1000	41.269	4.022	1005.49	5.49
1100	45.108	4.396	1099.03	-0.97
1200	48.828	4.759	1189.67	-10.33